

## Product Change Notice

PCN-R240802

Date of Publication: 2024/08/02

### Description of Change:

Change DDR due to the original material is EOL.

### Affected Product Model No.:

RSB-3720CQ-ACA1E, RSB-3720CQ-ACA2E, RSB3720CQ2301-T, EPCR3720IQ2302-T, RSB-3720WQ-ACA1E, RSB-3720WQ-ACA2E, EPC-R3720IQ-ALA100, EPC-R3720IQ-ALA120, EPC-R3720IQ-ALA140, EPC-R3720IQ-ALA160, EPC-R3720IQ-ALA10B, EPC-R3720IQ-ALA12B, EPC-R3720IQ-ALA14B, EPC-R3720IQ-ALA16B, EPC-R3720IQ-ALA200, EPC-R3720IQ-ALA220, EPC-R3720IQ-ALA240, EPC-R3720IQ-ALA260, EPC-R3720IQ-AWA12B, RSB3720WQ2201-T, RSB3720WQ2102-T, RSB3720WQ2202-T, RSB3720WQ2204-T, RSB3720WQ2301-T, RSB3720WQ2403-T, RSB3720WQ2404-T  
ROM-5722CQ-REA1E, ROM-5722WQ-REA1E & ROM5722WQ2201-T

Original P/N	Replacement P/N
1410030387-01 (MT53E1536M32D4DT-046 WT:A)	1410034025-01 (MT53E1536M32D4DE-046 WT:C)
1410030878-01 (MT53E1536M32D4DT-046 AIT:A)	1410030878-11 (MT53E1536M32D4DE-046 AIT:C)

### Potential impacts to Customers:

PCB: no change required

OS: no change required

Driver: no change required

### Benefits or Impacts:

Quality Impact:  no  minor  major (Better product longevity.)

Function Impact:  no  minor  major

Reliability Impact:  no  minor  major

### Ordering Information:

No change.

### Effective Date:

Standard PN: Running change/ T-Part : By customer approve

<b>Issue by</b>	PM: Lucia. Yeh
-----------------	----------------