

# Product PCN Notification

## PCN-Q240916

### Key Characteristics of the Change:

Due to Renesas PMIC/RCD supply management issue, the DDR5 5600MT/s RDIMM with Renesas PMIC (part number: P8900-X0Z001FNG8) /RCD(part number: RG5R256A1C0GBY) will discontinue, and will change to Montage PMIC(part number: M88P5000A4)/ Rambus RCD(part number:RCD5RCD2\_G1B)

### Description of Change to the Customer:

We hereby announces this will be the replacement which without any function impact for this change.


Product change will execute from Sep, 16th, 2024 (Track by SN#)

For example: serial number on the label: XXXX240916XXXXXXXX.

### Customer Impact of Change and Recommended Action:


The new PMIC/RCD effective change Date will be after **Sep, 16<sup>th</sup>, 2024.**

● **PMIC VERSION**

Renesas PMIC(OLD)	Montage PMIC (NEW)
	
Renesas RCD(OLD)	Rambus RCD(NEW)
	



Enabling an Intelligent Planet



**Product Affected:**

Model	PCN Announcement	Effective change Date	Replacement
SQR-RD5N16G5K6SZZB	Sep, 16 <sup>th</sup> , 2024	Sep, 16 <sup>th</sup> , 2024	The P/N remains the same
SQR-RD5N32G5K6SZZB	Sep, 16 <sup>th</sup> , 2024	Sep, 16 <sup>th</sup> , 2024	The P/N remains the same
SQR-RD5N32G5K6HZZB	Sep, 16 <sup>th</sup> , 2024	Sep, 16 <sup>th</sup> , 2024	The P/N remains the same